MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_47 NR_11_W.

			COUNTY
DESCRIPTION	OF	CORNER	_Sestion_Corner common to Sections 22,23,26,27
DESCRIPTION	OF	CORNER	MONUMENT_1 Pipe with A Brass sep
WIT TNESSES	то	CORNER	_305 No Pine Stub = 8 52 E = 153 Links
			_24! F. Pine. Stub = F 12 E = 165 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was 'ewnd by Ferestry Division survey crew, while making a partial reservey of this Tewnship. Two original B.T.'s still in place, poor

Corner was placed and witnessed July 10, 1952.

SURVEYORS SEAL

SIGNED CONTROL DATE 3/23/53_
REGISTERED LAND SURVEYOR