MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T. 47. NR . 11. F.

			Luse COUNTY
DESCRIPTION	OF	CORNER	1/4 Cerner between Sections 22.8.27
DESCRIPTION	OF	CORNER	MONUMENT_1"_Pipe_with_A" Breas_cap
WIT TNESSES	то	CORNER	10" Y. Pine 8.85 E 61 Links
			_ 5"_ WPine M_79 H = 90_Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Ferestry Division survey crew, while making a partial reservey of this Tewnship. One original B.T. still in place, poor condition.

Corner was placed and witnessed July 10, 1952.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 3/23/59