LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. 4 Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 47 N. x S., R. 11 x W.	L-6
2. PROPERTY CONTROLLING IN SECTION 13	,T. 47 N. x S., R. 11 x W.	4-Sec.13 6-Sec.13 8-Sec.13
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 9/23, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

L-6 Center Corner, Section 13.
4-Sec.13 Northwest 1/16 Corner, Section 13.
6-Sec.13 Northeast 1/16 Corner, Section 13.
8-Sec.13 West 1/16 Corner, Section 13.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-6 Placed corner at intersection of lines connectting opposite ¼ Corners.
4-Sec.13 Placed corner at center of NW Quarter Section.
6-Sec.13 Placed corner at center of NE Quarter Section.
8-Sec.13 Placed corner midway between Center of Section and West ¼ Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at all corners. (L-6 is buried in South rut of E-W road

L-6 Bearings: 6" W. Pine, S30°E, 45.4' & 24" W. Pine, N27°W, 41.6'.
4-Sec.13 Bearings: 7" Hard Maple, S68°E, 22.9' & 8" Hard Maple, S4°W, 19.5'.
6-Sec.13 Bearings: 12" R. Pine, S78°W, 14.5' & 8" R. Pine, S11°E, 15.9' & 8" R. Pine, N73°E, 20.9'
8-Sec.13 Bearings: 16" Beech, S60°E, 2.1' & 22" Soft Maple, S54°W, 35.2'.

SIGNED BY Billy D. Buckler DATE 9/8/78

Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

STATE OF MICHIGAN REGISTERED LAND SURVEYOR BILLY D. BUCKLER LAND SURVEYOR NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1973