LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

LUCE CO. 3 CORNERS

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER
L. PEBLIC LAND SURVEY.	$T_{\rm color} = 1, \dots, \frac{N_{\rm col}}{S_{\rm col}}, R_{\rm color}$	E
2. PROPERTY CONTROLL- 26 ING IN SECTION	,T47 🕺 R11.	₹X 13, 9, 2
3. MISCLET ANEOUS PROPERTY IN SECTION = :	- ,T	E. W.
1. 1 O L NO , RECO	ORDED PLAT.	
5, PRIVATE CLAIMS,		

REGISTER OF DEEDS STAMP AND

A. Description of original monument and accessories and/or subsequent restoration:

- 13 S.E. 1/16 Corner of Section 26. Not previously set.
- 9 East 1/16 Corner of Section 26. Not previously set.
- 2 East 1/16 Corner on North side of Section 26. Not previously set.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 13 Corner set at the center of S.E. 1/4, Section 26 by closed traverse.
- 9 Corner set midpoint on line between computed center corner and East 1/4 Corner of Section 26 by closed traverse.
- 2 Corner set midpoint on line between North 1/4 Corner and N.E Corner of Section 26.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. DNR Monument set at all three corners.

13	Fence Iron,	N77°W,	7.7'	9 12"	R. Pine,	N47°W, 50.	7. 2	-12" Mapte,	N80°₩,	3.6'
	12" Maple.	North,	27.1'	12"	W. Pine,	North, 39.	9'	6" Maple,	N47°W,	10.0'
	10" Maple.	S17°E.	48.2'	4"	Maple.	N74°E. 21.	5'	5" Maple.	N80°E,	16.2'
	12" Cherry,	S20°W,	13.4'	12"	Maple,	N40°E, 5.	81	4" Haple,	S60°E,	25.4'

SIGNED BY

Genald L. Wiggins

SURVEYORS MICHIGAN REGISTRATION NO. 23521

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF BURVEY PARTY

APPROVED AND SIGNED BY.

DATE

DATE

SUBVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN 28 1971 REVISED MAY 14 1975

(BEAL)

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET