

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

U


Luce COUNTY  
T 47N R 12W

DESCRIPTION OF CORNER East 1/16 Cor. bet Secs. 29-32

CORNER MONUMENT 1" Pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7-26-71

WITNESSES TO CORNER..... 7" Jack Pine (E 1/16 BT) S44°E 65.0'



36" W. Pine stub (E 1/16 BT) S70°W 22.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. Sec. Cor. to East and  $\frac{1}{4}$  Cor. to West.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

9-22-71

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing ←

R 4047  
Rev. 10/68