

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 47N R 12W

DESCRIPTION OF CORNER West 1/16 Cor. bet. Secs. 29-32

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED _____

WITNESSES TO CORNER..... 9" Jack Pine (W 1/16 BT) S68°E 13.4'



8" Jack Pine (W 1/16 BT) S10°W 8.4'

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. Sec. Cor. to West and $\frac{1}{4}$ Cor. to East.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE 9-22-71
Billy D. Buckler
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68