## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

Luce

\_COUNTY

	T <u>47</u> N R <u>12</u> W
DESCRIPTION OF CORNER t Cor. bet. Se	ecs. 20-29
CORNER MONUMENT 1" pipe with 4" aluming	ım cap.
DATE MONUMENT PLACED AND WITNESSED 7-	-171
WITNESSES TO CORNER 10" Jack Pine	: (±s nbt) n74°w 11.4°
20	( <del>L</del> S NBT) S42°E 44.1°
AND	
CIRCLE CORNER REGISTERED	
DESCRIPTION IN DETAIL AS TO HOW CORNER WA	S LOCATED AND IDENTIFIED OR RESTORED.
This corner re-established midway and or	line bet. two Sec. Cors.
Several old W. Pine stump bottoms but no Position fits record call to a small man	one could be identified as original witness. sh to west.
	,7
SURVEYOR'S SEAL	My De Buckler DATE 8-16-71
31MILD	V D. Buckler DATE 8-16-71 RED LAND SURVEYOR
County Courthouse Area Forester (Regions I & II) District or Region Surveyor	
Forestry Div., Lansing	R 4047

R 4047 Rev. 10/68