## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	Luce		COUNTY	
	T	47N	. R_	12W
DESCRIPTION OF CORNER # Cor. bet. Secs. 21-28				
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap	· · · · · · · · · · · · · · · · · · ·			
DATE MONUMENT PLACED AND WITNESSED 6-25-71				
WITNESSES TO CORNER 5" W. Pine (LS NBT) N35°W	3.81			
9" W. Pine (±S NBT) N16°E	27.8			
AND				
CIRCLE CORNER REGISTERED		····		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from a W. Pine stump bottom, bearing S60°W, 35 links. Found no marks to identify this as a recorded witness but found corners to East and West. Proportionate measure falls close to this location. Distance East (525.0°) to top of a high bank as well as a stream (1208°) checks with record.

SURVEYOR'S SEAL

SIGNED

Silly W. Buckler

REGISTÉRED LAND SURVEYOR

DATE

9-30-71

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing