

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY  
T 47N R 12W

DESCRIPTION OF CORNER East 1/16 Cor. bet. Secs. 30-31

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 4-26-71

WITNESSES TO CORNER..... 10" Jack Pine (E 1/16 BT) S52° 5.7'



6" Jack Pine (E 1/16 BT) N10°E 33.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway bet. Sec. Cor. to East and  $\frac{1}{4}$  Cor. to West.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler

DATE

9-30-71

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68