STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	Luce	COUNTY
	T <u>47N</u>	R 12W
DESCRIPTION OF CORNER Sec. Cor. common to Secs. 29	9-30-31-32	
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.		
DATE MONUMENT PLACED AND WITNESSED4-23-71		
WITNESSES TO CORNER 6" W. Pine (S30 NBT) N67°W 1	0.2	
8" Jack Pine (S29 NBT) N78°E	E 40.81	- 140
9" Jack Pine (S31 NBT) S2 ^o W AND	53.51	· · · · · · · · · · · · · · · · · · ·
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established on line and by proportionate distance between Sec. Cor. one mile South and Sec. Cor. one mile North.

The original corner was placed on a straight, three mile line.

Found an original line tree on the mile to North, fonforming to this location.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler D

REGISTERED LAND SURVEYOR

DATE _

9-28-71

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68