

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

V


Luce COUNTY
T 47N R 12W

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 31-32

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4-26-71

WITNESSES TO CORNER..... 10" Jack Pine (¼S NBT) N13°W 11.0'



9" Jack Pine (¼S NBT) S60°W 38.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. Cors. Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

Billy D. Buckler

DATE 9-30-71

REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68