

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY
T 47N R 12W

DESCRIPTION OF CORNER North 1/16 Cor. bet. Secs. 31-32

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 4-26-71

WITNESSES TO CORNER..... 7" Jack Pine (N 1/16 BT) N10°W 1.2'



10" Jack Pine (N 1/16 BT) S68°E 12.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line bet. Sec. Cor. to North and $\frac{1}{4}$ Cor. to South.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 9-28-71
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68