STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

	Luce	COUNTY
	T <u>47N</u>	R <u>12W</u>
DESCRIPTION OF CORNER		
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap		
DATE MONUMENT PLACED AND WITNESSED 7-2-71		
WITNESSES TO CORNER 6" Jack Pine (LS NBT) S270W	55.81	
8" Jack Pine (±S NBT) N41°W	49.01	
AND		
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner re-established midway and on line bet. two Sec. Cors. Found no evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED

9-28-71 DATE

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor

Forestry Div., Lansing

Rev. 10/68