STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	-	Luce	COUNTY
	τ	47N	R
DESCRIPTION OF CORNER ± Cor. bet. Seds. 19-	50		
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap	<u> </u>		
DATE MONUMENT PLACED AND WITNESSED 5-25-73	L .		
WITNESSES TO CORNER 5" Jack Pine (如 Ni	3T) N58 ⁰ W 12.	,gı	
N 12" Jack Pine (\$\frac{1}{4}\$ N)	ЭТ) N23 ⁰ E 39	.21	
AND			
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This currer replaced from remains of two original witnesses; a W. Pine stump, bearing N48°E, 08 links and a W. Pine stump, bearing S31°W, 17 links. Both stumps show evidence of a blaze and notch. Found an old post at this corner.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

DATE

9-30-71

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68