

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co.

FOR CORNERS OF --:	LOCATED IN --:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>48</u> N. <u>2</u> R. <u>8</u> E. <u>W.</u>	C-5
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

Filed 6-30 A.D. 1972  
 At 3:40 o'clock P.M.  
 File No. 54  
*Doris Taylor Dep.*  
 Luce County Reg. of Deeds  
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 5/1 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

Sec. Cor. 7-8-17-18, originally set by Wells Burt, D.S. 1850.  
 Bearings were:  
     Sugar      N50°W    23 Links  
     Beech      S57°E    31 Links

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

Found two 6" Concrete posts, 50.0' North and 50.0' South of Sec. Cor. which is located in Center of M-123. Corner perpetuated by Luce Co. Road Commission.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Re-witnessed Corner location.  
 New Bearings:

Maple 6"    N41°W    53.7'  
 Maple 8"    S11½°E   37.4'

SIGNED BY *Billy D. Buckler* Billy D. Buckler DATE 6/20/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

**FOR STATE AND UNITED STATES AGENCIES:**

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR DATE \_\_\_\_\_ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_