CON 8. 40 47 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 48 N.R. SX.

Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 16-21

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 9/3/67

WITNESSES TO CORNER. 6" Aspen (1/45 NBT) S65°W 33.0!

48" W. Fine Stub (NBT) N70°W 91.6!

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at wood post, midway and on line between two Section Corners. Found no evidence of Original Corner, but found squared post in place. Corner lies on South edge of a woods road.

Corner found by L. Rubick, Aide

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Billy D/ Buckler DATE 10/25/67
REGISTERED LAND SURVEYOR