

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD


Luce COUNTY  
T 48N R 8W

DESCRIPTION OF CORNER South 1/16 corner bet. Secs. 7-8

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5-12-69

WITNESSES TO CORNER..... 9" Y. Birch (1/16 BT) S40°E 6.0'



9" Soft Maple (1/16 BT) S52°W 10.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between  $\frac{1}{4}$  corner to North and Sec. Cor. to South.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

6-19-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68