

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Luce
_____ COUNTY
T 48N R 8W

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. Secs. 9-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4/14/72

WITNESSES TO CORNER..... 14" Dead Cedar Stub ($\frac{1}{4}$ S NBT) S37°E 21.0'



9" Dead Cedar Stub ($\frac{1}{4}$ S NBT) N55°E 8.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a scribed wood post, placed by H. Lawrence, R.L.S.
Found remains of one original witness; a Cedar Stump bearing S40°E, 06 Links.

Corner lies in an area of dead cedar with small reproduction, very wet.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 4/19/72

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68