LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

2 Corners.

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	1
1. PUBLIC LAND SURVEY	T N F		-
2. PROPERTY CONTROLL- 8	,T48 N 8 T	7. 3	
3. MISCELLANEOUS PROPERTY IN SECTION —	N. S., R F	:	-
4. LOT NO, REC	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
and rules therefore as required: Bureau of Land Management or and 5 above were, in a field surv	in the current manual of surv by a decree of a court of law ev on	vey instructions of the United v. Furthermore, that the corne	of P.A. 74, Michigan P.A. of 1970 9-19, 1983, established d in conformance with regulations States Department of the Interior, per points mentioned in lines 3, 4 stored, established or re-established tration for Land Surveyors or, by a
A. Description of original monu	ment and accessories and/or	subsequent restoration:	
		ion 8. Not prev. est.	
3 West 1/16 corner o	f section 8. Not pr	ev. est.	
B. Description of corner evidence 7 Corner set M.P.O.L.	e found and/or method appli between NE corner a	ied in restoring or re-establishin and East 1/4 corner of	g corner:
		orner and computed cen	
C. Description of monument for a DNR Monument set at bot 7 8" Cedar, S40°E, 7" Cedar, N81°W, 14" Hemlock, N20°E, 6" R. Maple, N2°W,	h corners. bearings 19.75! 12.80! 27.60!	3 7" b. Maple, 8" Spruce, 12" Eeech,	West, 31.40' N60°W. 29.40'

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)