LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

1 Corner

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 48 N. R. 8 XX	A-7	
2. PROPERTY CONTROLL- ING IN SECTION——	N. E. V. S., R. W.		
3. MISCELLANEOUS PROPERTY IN SECTION.	· ·		
4. LOT NO, REC	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
and rules therefore as required: Bureau of Land Management or and 5 above were, in a field surv	in the current manual of survey by a decree of a court of law.	v instructions of the United S Furthermore, that the corne 19, found, recovered, res	of P.A. 74, Michigan P.A. of 1970, 1984, established, d in conformance with regulations states Department of the Interior, r points mentioned in lines 3, 4 tored, established or re-established ration for Land Surveyors or, by a
A. Description of original monu	ment and accessories and/or su	bsequent restoration:	
A-7 N.W. Section Corner	of Section 19. Wood	Post. OBT'S: Sugar Beeck Beeck Beeck	c 6, S8 ⁰ W, 30 lks. n 6, N16 ⁰ W, 6 lks. n 12, N35 ⁰ E, 16 lks. n 10, S17 ⁰ E, 25 lks.
B. Description of corner evidence A-7 Corner set M.P.O.L. Section 19. C. Description of monument for	between West 1/4 Cor	ner of Section 18 and	West 1/4 Corner of
	earings: 7" H. Maple 6" Beech, 7" Beech,		position or the corner:

SIGNED BY DATE 9-17-84

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(ORAL)