LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

L	UCE (County)	Located In:	Corner Code ≠
1.	Public Land Survey	T48N R8W	К-3
		T R	
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat ...

5. Private Claims

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- S.W. Section Corner of Section 1. OBT'S: Beech 8", N56°E, 19 1ks. & Beech 5", S45°W, 8 1ks.
- 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

Set corner at intersection of N-S and E-W old blazed lines. Corner set 133.6' south of center line M-123 as shown on road construction plans and M.D.O.T. right of way plans. Distance South to river fits original, as well as distance East to original meander corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

DNR monument placed at corner. 28" Hemlock, SO5°E, 56.8' 10" Hemlock, N65°W, 39.92' 14" Beech, 8060°E, 38.15' 20" Spruce, \$36°W, 25.0'

Signed by Jesald & Auggins
Surveyor's Michigan License No. 23521

2-26-90

FORM APPROVED BY MICHIGAN STATE SALES AN

AB OF LAMO BUNYEYORS, JAN. 20. 191 REVISED MAY 10. 191 BUYEER JAN., 191

WIGGINS

23521

e <u>2-20-90</u>