

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48-49 N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER East 1/16 corner between Secs. 2-35

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7/19/68

WITNESSES TO CORNER..... 12" R. Pine (E1/16 BT) S38°E 17.9'



10" R. Pine (E 1/16 BT) N10°E 30.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner is established between section corner to East and $\frac{1}{4}$ corner to West.

Found old blazes on line.

Corner lies on hillside, 20' West of swamp edge.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler, R.L.S. DATE 9/13/68
REGISTERED LAND SURVEYOR