

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48 N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between secs. 3-10

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7/16/68

WITNESSES TO CORNER..... 12" W. Pine (1/8 S NBT) North 20.7'



9" Tamarack (1/8 S NBT) S58°W 22.0'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established between a good section corner to West and a good meander corner to East. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler R.L.S. DATE 9/12/68
REGISTERED LAND SURVEYOR