

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>46</u> N. <u>X</u> , R. <u>9</u> E. <u>W.</u>	J-9
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. _____ E. _____ S., R. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. _____ S., R. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

Filed 6-30 A.D., 1972
 At 4:30 o'clock P.M.
 File No. 57
Doris Taylor, Dep.
 Luce County Reg. of Deeds

 REGISTER OF DEEDS STAMP AND
 FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 5/3 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
1/4 Corner bet. Secs. 23-26.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
 Found two concrete, witness posts, set by Luce County Road Commission.
 Corner lies in eastside, M123 and 11.0' East of center line, M-123.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 Re-witnessed Corner perpetuated by Road Commission.
 New Bearings:
 12" Beech S22°E 35.5'
 26" Beech N63°W 52.4'

SIGNED BY Billy D. Buckler *Billy D. Buckler* DATE 6/26/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR DATE _____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____