

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~48~~ NR 8-2 W

----- *Luce* ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 7-18-12-13 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 30" W. Pine ----- N 53° E ----- 21 links

"S 7 NBT"

10" Cedar ----- S 6° W ----- 48 links

"S 13 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced corner from one Cedar B.T. (down) in good condition and one
Hemlock B.T. in poor condition.

Found post set by H. Lawrence, Reg. Surveyor.

Corner shown to us by B. McTiver, District Forester.

Corner placed & witnessed Dec. 12, 1957.

SURVEYORS SEAL

SIGNED *Billy D. Buckler* DATE 12/19/57
REGISTERED LAND SURVEYOR