## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_48\_ NR\_9\_W

	LuceCOUNTY
DESCRIPTION OF CORNER 1/4 corner bet	tween Sections 2 and 3
DESCRIPTION OF CORNER MONUMENT	1" Pipe with 4" Brass Cap
WITNESSES TO CORNER _ 10" Red Pine .	(1/4s NBT) N 17. W 26-Links-
10" Red Pine	_(1/4s_NET) _ S 80° E _ 06 Links _

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one W. Pine B.T. bearing S 80° E, 35 Links. Tree down and in poor condition. Found scribe marks and notch on several pieces of wood. Numerous blazes in vicinity of corner. Corner lies on steep hillside facing to south. Squared and scribed 10° Red Pine at corner.

Corner was placed and witnessed July 27, 1960 with L. Rubick, Aide, Newberry.

SURVEYORS SEAL

SIGNED \_\_\_\_\_\_ DAT

REGISTERED LAND SURVEYOR

Billy D. Buckler