

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 48-49 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER  $\frac{1}{4}$  Corner between Secs. 3-34

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7/12/68

WITNESSES TO CORNER.....9" W. Pine ( $\frac{1}{2}$ S NBT) S26°W 54.9'



8" Red Pine ( $\frac{1}{2}$ S NBT) S14°E 63.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established along East-West township line by single proportionate measure, found blazes along this line.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler R.L.S. DATE 9/13/68  
REGISTERED LAND SURVEYOR