

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48-49 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Corner common to Secs. 2-3-34-35.

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7/19/68

WITNESSES TO CORNER..... 7" R/ Pine (S2 NBT) S47°E 28.2'



8" R. Pine (S34 NBT) N55°W 37.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by single proportionate measure,
along East-West township line.

Corner lies in wet spruce marsh and southwest of a small lake.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler R.L.S. DATE 9/13/68
REGISTERED LAND SURVEYOR