

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 48. NR. 10 W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 4, 5, 8, 9 . . . .

DESCRIPTION OF CORNER MONUMENT 1/2" x 36" steel bar . . . . .

WITNESSES TO CORNER 14" H. Maple ----- N 1° E ----- 40 links .

6" H. Maple ----- S 29° W ----- 24 links .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Maple B.T. (down) in poor condition.

Placed 1/2" x 36" steel bar in south edge of East and West road.

Placed Post 5' south of corner. Noted: S.

C.  
5'  
N.

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed August 2, 1956.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

DATE 8/17/56