

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48 NR. 10 W.

Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 29-32

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 11" Hemlock N 35° E 65 links

14" Beech S 27° W 80 links
"1/4 S NBT"
"1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from one soft maple B.T. bearing N 70° E 5 links.

Found notch and overgrowth in stump. Tree has been cut recently.

Found wood post in place.

Corner found by B. McTiver, District Forester.

Corner placed and witnessed Dec. 18, 1957.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 12/18/57