Coms. 40 47 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 47 & 48 N.R. 10W

	Luce	COUNTY
DESCRIPTION OF CORNER 1/4 Corner between Secs. 1 2	2, T47M R10W & 35, T48M R10M	
CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Car	0	
DATE MONUMENT PLACED AND WITNESSED 3/17/64		
WITHESSES TO CORNER 4" B Spruce (2S LBT) S23	W 24 Lics.	
6" J. Pine (2S 1BT) N10°	W 76 14s.	
AND CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on Line between Section Corners.

SURVEYOR'S SEAL

SIGNED Frank J. Fray DATE 8/1