

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 & 48 N.R. 10W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1,2 T47N R10W & 35,36 T48N R10W

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 3-17/64

WITNESSES TO CORNER..... 5" E. Spruce (S36 NBT) N24°E 68 Lts.



8" dead J. Pine (S2 NBT) S61°W 29 Lts.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was re-established by Single Proportioned measurement between Town Corner to East and 1/4 Corner  $3\frac{1}{2}$  miles West and on Line between said Corners.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 8/17/1964  
REGISTERED LAND SURVEYOR