

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 S 48 N.R. 10W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Secs. 5, T47N R10W, 32, T48N R10W.

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 3/18/64

WITNESSES TO CORNER..... 7" Cedar (1/2 S NBT) N45°W 13 Lks.



5" Cedar (1/2 S NBT) S76°E 39 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from old Wood Post. Several Blazes on trees in vicinity. No original evidence. Checks well for distance to Corners East and West.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 8/17/64
REGISTERED LAND SURVEYOR