LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

1 Corner

FOR CORNERS OF -:	LOCATED IN -:		CORNER CODE NUMBER
1, PUBLIC LAND SURVEY	T. 48 N., R. 10	_ X . _ W.	_L-7
2. PROPERTY CONTROLL- ING IN SECTION——	,T S., R	E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T ^{N.} S., R.	E. W.	
4. LOT NO	CORDED PLAT		
5 PRIVATE CLAIMS			

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, __sivid b, Babbitt ______, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner poirts mentioned in lines 1 and 2 above were, in a field survey on ________, 19_82, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ________, 19______, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
- -7 1/4 Cor. on north side of sec. 24. Wood Post, Cedar 10", N9°W, 20 lks. & Spruce 8", S28°E, 20 lks.
 - B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- -7 Set corner from original ET: Cedar 10", N9°W, 20 1ks.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- -7 D.M.R. Mcnument. New Bearings:
 - 2:" Cedar, NO9 W, 12.8' 1:" Cedar, S88 E, 40.3'
 - 10" Cedar, S54W, 8.4' 2" Cedar, N660W, 16.5'

SIGNED BY Wail B. Ball	itt	DATE 8-3-8
Lavid E. Babbitt		
SURVEYOR'S MICHICAN RECISTRATION NO	21558	

(SEAL)

FOF STATE AND UNITED STATES AGENCIES: