

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48. NR 11. - 12 W

... L u e e ... COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 7, 18, 12,
and 13

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" Cedar (S 18 NBT) S 35° E - 26 Links

6" Cedar (S 7 NBT) N 33° E - 14 Links

9" Cedar (S 13 NBT) S 77° W - 55 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from original B. T.'s. Several
Tamarack stumps in proper positions. Found wood post in place with
Hemlock line tree 9.20 chains to south of corner.

Corner placed and witnessed January 21, 1960 with L. Rubick and R.
Norkali.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 2/23/60