

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48 N.R. 11 W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner for Secs. 9/10-15-16

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/2/65 with L. Rubick

WITNESSES TO CORNER..... 24" W. Pine (S 15 NBT), S 33° E, 36 Lks.



CIRCLE CORNER REGISTERED

10" Cedar (S 10 NBT), N 33° E, 70 Lks.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from original BT (Cedar 14" S 43° E, 40 Lks.) which is leaning but still growing. Rotted Spruce stump in place.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/16/1965
REGISTERED LAND SURVEYOR