

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 48N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER ¼ Cor. bet. Secs. 17-18

CORNER MONUMENT 1" pipe with ¼" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7-9-70

WITNESSES TO CORNER..... 20" Hard Maple (½S NBT) N69°E 4.0'



18" Hard Maple (½S NBT) S21°W 23.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at a Hard Maple tree, blazed on all sides. Numerous blazes facing this location on several adjacent trees.

Distance south to a hemlock line tree checks well.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE 1-20-71  
REGISTERED LAND SURVEYOR