Cons. 4047 4/96

## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 48 NR 10-11 W

	Luce	COUNT
DESCRIPTION OF CORNER	Section corner common to Sec.	<b>s</b> 18-19-13-24
DESCRIPTION OF CORNER	MONUMENT 1" pipe with 4" br	ass cap
WITNESSES TO CORNER	5" Tamarack N1°E	52½ links
	"S 18 NBT"  5" Tamarack S 30° W	39 <u>links</u>
	"S 24 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner as set by H. Lawrence, Reg. surveyor.

Found wood post in place and checked two tamarack stump bottoms, bearing S 33° E 20 links and N 75° E 37 links.

Corner found by B. McTiver, District Forester.

Corner lies in open tamarack marsh.

Corner placed and witnessed Dec. 18, 1957.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 12/18/57
REGISTERED LAND SURVEYOR