LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

FOR CORNERS OF -:

LOCATED IN -:

1 Corner

CORNER CODE NUMBER

1. PUBLIC LAND SURVEY T S., R E	
1. PUBLIC LAND SURVEY T S., R W.	
2. PROPERTY CONTROLL. 6 ,T. 48 %, R. 11 V. 2-Sec.6	
3. MISCELLANEOUS PROPERTY IN SECTION, T S., R	
4. LOT NO, RECORDED PLAT	
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Billy D. Buckler , do hereby certify that under requirements of	f P.A. 74, Michigan P.A. of 1970,
the corner points mentioned in lines 1 and 2 above were, in a field survey on 9-11 re-established, monumented, re-monumented, recovered or restored as expressed below and and rules therefore as required in the current manual of survey instructions of the United S Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner and 5 above were, in a field survey on 19, found, recovered, rest as expressed below and in conformance with the rules of the Michigan State Board of Registr Decree of a Court of law:	in conformance with regulations tates Department of the Interior, points mentioned in lines 3, 4 ored, established
A. Description of original monument and accessories and/or subsequent restoration:	
2-Sec.6 East 1/16 Corner on Northeide of Section 6.	
B. Description of corner evidence found and/or method applied in restoring or re-establishin	g corner:
2-Sec.6 Placed corner midway and on line between section corner t	o East and 1/4 corner to West.
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
2-Sec.6 Placed a 1" pipe with 4" dep't cap at corner. Bearings	:

SIGNED BY DATE9-14-81

Billy D. Buckler

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

12" R. Maple, N41 E, 22.85' & 12" W. Pine, N74 W, 33.0' & 14" W. Pine, S1 E, 38.7'.