LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

1 Jorner

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 48 N. R. 11 W.	J-3 /	
2. PROPERTY CONTROLL- ING IN SECTION——	,T N. R E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. E. W.		
4. LOT NO, RECO	RDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I, David F. Babbitt , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 11-1 , 19 83, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on			
A. Description of original monum	ent and accessories and/or sul	bsequent restoration:	
J-3 1/4 corner on south	n side of section 2.	ObT'S: Wood Post,	9" W. Pine, S25 ^O E, 14 lks. & 9" Spruce, N52 ^O W, 16 ¹ lks.
B. Description of corner evidence J-3 Corner set at found		_	ng corner: ump in place for S.E. O.B.T.
C. Description of monument for a			position of the corner:
J-3 D.N.K. Monument.	dearings: 12" W. Bir 14" W. Bir 7" Gedar, 10" R. Map	ch, N32°E, 27.8' ch, N18°W, 37.3' S13°W, 20.9' de, S47°E, 14.3'	

SIGNED BY Avid B. Babbitt

David B. Eabbitt

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)