LAND'CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

2

3 Corners.

	FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER		
	1. PUBLIC LAND SURVEY	T S., R W.			
	2. PROPERTY CONTROLL- 3 ING IN SECTION 3	,T. 48 N. R. 11 W.	2, 14, 16		
	3. MISCELLANEOUS PROPERTY IN SECTION	, T S., R E.			
	4. LOT NO, RECORDED PLAT				
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER	
	David B. Babbitt I, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 19				
	the corner points mentioned in lines 1 and 2 above were, in a field survey on 12-12 & 12-13 , 19 84, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on				
2	A. Description of original monument and accessories and/or subsequent restoration: East 1/16 Corner on north side of section 3. Not prev. set.				
14	South 1/16 corner on east side of section 3. Not prev. set.				
16	East 1/16 corner on south side of section 3. Not prev. set.				
2	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Corner set M.P.O.L. between the North 1/4 Corner and the N.E. Section Corner of Section 3				
14	Corner set M.P.O.L. between East 1/4 Corner and S.E. Section Corner of Section 3.				
16	Corner set M.P.O.L. between South 1/4 Corner and S.E. Section Corner of Section 3.				
D.N	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: D.N.R. Monument set at all three corners. Bearings:				
2	10" W. Pine, NO3 ^O W, 7.1' & 12" W. Pine, S83 ^O E, 42.6' & 10" W. Pine, S18 ^O E, 37.85' & 5" W. Pine, S30 ^O W, 18.5'.				
14	8" Tamarack, N78 ⁰ E, 45.8' & 5" Tamarack, N49 ⁰ W, 14.2' & 7" Tamarack, S37 ⁰ E, 36.2' & 6" Spruce, S28 ⁰ W, 41.7'.				
16	7" Spruce, S26 ⁰ W, 16.9' & 6" Spruce, N16 ⁰ E, 10.5' & 7" Spruce, S59 ⁰ E, 8.5' & 7" Spruce, S21 ⁰ E, 17.1'.				
	SIGNED BY David B. Babb	B. Baffitt	DATE 3-4-8	5	
	SURVEYOR'S MICHIGAN REGI	ISTRATION NO. 21558	3	(SEAL)	