## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co.

3 Corners.

	Luce	60.	0 00,		
F	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER		
1	. PUBLIC LAND SURVEY	T. 48 S., R. 11 S	K-2, H-3		
2	2. PROPERTY CONTROLL- ING IN SECTION—2				
3	3, MISCELLANEOUS PROPERTY IN SECTION——	,T			
4	6, 1.OT NO, REC	CORDED PLAT			
5	5, PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER	
ī	David B. Babbitt	do hereby	certify that under requirements	of P.A. 74, Michigan P.A. of 1970,	
the corner points mentioned in lines 1 and 2 above were, in a field survey on 6-20 & 6-21 , 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:					
K-2	A. Description of original mon- East 1/4 Corner of S	ument and accessories and/or ection 2. Wood Post	subsequent restoration: . O.B.T.'S.: A Spruce Cedar 1	e 10" 1/4 Section Corner & .6", N84 <sup>0</sup> E, 54 links.	
H-3	South 1/4 Corner of	Section 3. Wood Post	. O.B.T.'S.: Spruce Spruce	10, S37½°W, 47 links & 10, N20°E, 20 links.	
7	7 North 1/16 Corner on East side of Section 2. Not prev. set.				
<ul> <li>B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:</li> <li>K-2 Set by single proportion to the G.L.O. Record using a line tree North and the S.E. Sec. Cor. of Section 2 South for control. Stream calls North and South also fit well.</li> </ul>					
H-3	Corner set M.P.O.L.	between the S.W. Sec	. Cor. and the S.E. Se	c. Cor. of Sec. 3.	
7	Set by single propor and a line tree on t	tion to the G.L.O. R he East line of Sec.	ecord between the East 2.	: 1/4 Corner of Sec. 2	
	C. Description of monument for R. Monument set at al		olished to perpetuate locating th	ne position of the corner:	
K-2	6" Cedar, S75 <sup>0</sup> E, 27. 6" Cedar, N40°W, 7.4	1' & 6" Cedar, S17 <sup>0</sup> W '.	, 32.9' & 10" Cedar, S	72 <sup>0</sup> W, 28.3' &	
H-3	3" Tamarack, N28 <sup>O</sup> E, 8" Tamarack, S09 <sup>O</sup> W,	15.3' & 8" Tamarack, 64.5'.	S62 <sup>0</sup> E, 44.4' & 6" Tam	marack, S23 <sup>0</sup> E, 69.2' &	
7	20" W. Pine, S12 <sup>o</sup> W, 10" W. Pine, N80 <sup>o</sup> E,	25.2' & 20" W. Pine, 38.1'.	S56 <sup>0</sup> W, 22.7' & 14" W.	Pine, N33 <sup>0</sup> W, 50.8'	
5	SIGNED BY Davis	B. Bassitt	DATE_7-19-	-85	
5	David B. Bab SURVEYOR'S MICHIGAN RE	bitt GISTRATION NO. 21558		(SEAL)	

FOR STATE AND UNITED STATES AGENCIES: