

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48-49 NR. 12 W. . .

. . . Luce COUNTY

DESCRIPTION OF CORNER . . . Section Corner common to Sections 33, 34, 3, 4 . . .

DESCRIPTION OF CORNER MONUMENT . . . 1" pipe with 4" brass cap

WITNESSES TO CORNER . . . 12" Cedar N 45° W 42 links

. . . 10" Cedar N 73° E 35 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from two original B.T.'s in poor condition.

Corner shown to us by Bernard McTiver, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 6/13/56
REGISTERED LAND SURVEYOR