

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48-49 NR. 12 W. . .

----- Luce ----- COUNTY

DESCRIPTION OF CORNER 1/4 Section Corner between Sections 3 and 34 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 14" Cedar ----- N 55° W ----- 45 links -----

7" Cedar ----- S 30° W ----- 9 1/2 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one Cedar and one White Birch B.T.'s in: Cedar - good and Birch poor condition.

Corner shown to us by Bernard McTiver, District Forester.

Corner placed and witnessed June 12, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 6/13/56
REGISTERED LAND SURVEYOR