

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 48 .. NR. 12 .. W

.. L u c e .. COUNTY

DESCRIPTION OF CORNER 1/4 corner between Section 12 and 13 ..

DESCRIPTION OF CORNER MONUMENT .. 1" Pipe with 4" Brass Cap. ..

WITNESSES TO CORNER .. 10" Hemlock .. (1/4s NBT) .. N 12° E .. 47 Links ..

10" Hemlock .. (1/4s NBT) .. S 65° W .. 26 Links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced from one Cedar B. T. bearing N 69° W 05Links
Stump in poor condition.

Corner lies in swamp.

Corner was placed and witnessed January 21, 1960 with L. Rubick and R. Norkali.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/23/60 ..