

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 49 N.R. 9 W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 13 and 24

CORNER MONUMENT _____

DATE MONUMENT PLACED AND WITNESSED 5/2/61 with L. Rubick

WITNESSES TO CORNER... 12" Soft Maple (1/4s NBT) N 27° W 58 Links



10" Soft Maple (1/4s NBT) S 74° E 70 Links

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed. Both Hemlock NBT's bearing N 39° W, 83½ Links and S 86° W, 38½ Links are dead but still standing. These trees were marked by myself in 1956.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 26, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler