

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luce _____ COUNTY


T 49-50N R 9W

DESCRIPTION OF CORNER West 1/16 Cor. bet. Secs 33-4

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/8/71

WITNESSES TO CORNER..... 8" J. Pine North 31.6'



8" R. Pine S3°W 106.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed midway and on line bet. Sec Cor. to west and $\frac{1}{4}$ Cor. to east.

Corner lies 6.0' north of E-W fireline.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 12/17/71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68