

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luca _____ COUNTY


T 49-50N R 9W

DESCRIPTION OF CORNER East 1/16 Cor. bet. Secs. 33-4

CORNER MONUMENT 1" Pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7/8/71

WITNESSES TO CORNER..... 12" J. Pine S05°W 26.6'



6" R. Pine N10°W 25.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
Corner lies in south rut of E-W fireline.

Corner placed midway and on line bet. Sec. Cor. to east and $\frac{1}{4}$ Cor. to west.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 12/17/71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68