STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

1	

			Luce	COUNTY R 9W
			T49N	
DESCRIPTION OF CORNER	Cor. bet. Secs.	5-8		
CORNER MONUMENT 1" pipe	with 4" aluminum	cap		
DATE MONUMENT PLACED AND W	IITNESSED 6/25/71			
WITNESSES TO CORNER	5" J. Pine S50	ow 35.81		
N	7" J. Pine N35	OE 31.91		
5		·		
	AND			
CIRCLE CORNER REGISTERE	 D			<u> </u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established midway and on line bet. two Sec. Cors.

Corner lies in south rut of E-W fireline.

SURVEYOR'S SEAL

SIGNED

Billy D/ Buckler

DATE 12/17/71

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing