

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Luce COUNTY


T 49N R 9W

DESCRIPTION OF CORNER West 1/16 Cor. bet. Secs. 3-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/25/71

WITNESSES TO CORNER..... 8" J. Pine S50°E 43.7'



8" J, Pine N47°E 66.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
Corner placed midway and on line bet. Sec. Cor to west and $\frac{1}{4}$ Cor. to east.

Corner lies in south wheel rut of E-W fireline.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 12/17/71
Billy D. Buckler
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68